

Architect's Clarification:

Fireproofing should be provided on the steel ledger angle that holds up the PT slab at the stair core in the garage. See Structural detail 18/S510.