

Rapid Fire Protection, Inc. questions asked:

Answers to Q 1-4 below, by Lantz-Boggio Architects, PC.

Christenson Construction, Inc. (CCM) answered No. 5.

1. Does the attic require protection? It is non combustible and should not have to be covered but the code sheet says that it does require coverage.

The attic is inaccessible and of non combustible construction, therefore under the NFPA, sprinklers in this area are not required. Disregard note on Code Sheets requiring the sprinklers.

2. The piping required by the specification is schedule 40 astm 53/A795 seamless black steel pipe. Is this really what the mechanical engineer is wanting us to use? Seamless pipe is extremely expensive and is not typically used on a project like this.

Disregard specification requirement for "seamless" pipe. Standard piping that meets the codes for this type installation is acceptable.

3. Which type of pendant head is required flush/concealed or semi recessed? They is a big cost difference between the two.

Semi-recessed heads throughout.

4. The garage areas show unit heaters is a dry system still required in this area?

No dry system. The unit heaters were added to keep the space temperate and at about 55 to 58 degrees.

5. Can the most current WY Prevailing Wage Scale be provided?

Prevailing Wages Are Not Required On This Project - (CCM)